



FIG. 1




09832115.041101

FIG. 2



109832115.041101

FIG. 3



09332116 "041101

FIG. 4




FIG. 5A




FIG. 5B




FIG. 5C





FIG. 6



0903216-041101

FOFH0"9TT2E2B0

FIG. 7

2000P ACCUMULATIVE ERROR






FIG. 8



0983216-041101

FIG. 9



09832115, 041101

FIG. 10









FIG. 10

FIG. 11




109832116.041101

FIG. 12




09832115-041101

FIG. 13



09832116.041101

FIG. 14



09832116.04.11.01

FIG. 15A




FIG. 15B




FIG. 16A




FIG. 16B




FIG. 17A




FIG. 17B




FIG. 18A




FIG. 18B




FIG. 19A




FIG. 19B




FIG. 20




FIG. 21




FIG. 22



0003215.04101
FIG. 22

FIG. 23



09832416-041101

FIG. 24




FIG. 25




FIG. 26




FIG. 27A




FIG. 27B




FIG. 27C




FIG. 28




FIG. 28

FIG. 29A




FIG. 29B




FIG. 29C





FIG. 29D



09332116-041101

FIG. 30A




FIG. 30B




FIG. 31A




FIG. 31B




FIG. 31C




FIG. 32A




FIG. 32B




FIG. 32C





FIG. 33

MRA ROTARY SCALE 103



DETECTION HEAD

09832116-041101

FIG. 34




FIG. 35




FIG. 36






FIG. 37



09032116-041101

FIG. 38



0913322116 041101

FIG. 39




FIG. 40




FIG. 40

FIG. 41




FIG. 42






FIG. 43




09332115-041101

FIG. 44



09032116.041.01

FIG. 45



09332116-041101

FIG. 46

